

To: Prospective Bidders

From: Brad T. McKeachnie, Procurement/ Compliance Analyst

Subject: ADDENDUM Number #1 to IFB #RTC10-5

Date: 2/17/2010

Date

This constitutes Addendum Number 1 to the **Invitation For Bid** for the Nortel telephony equipment, issued by the Regional Transportation Commission of Washoe County (RTC) on <u>2/2/2010</u>. This Addendum becomes part of the original IFB package and shall become part of the contract with the successful Proposer.

This Addendum is hereby issued to answer questions as listed and, to completely replace the previous equipment price sheet with the new one attached.

Bidders are required to sign and return this page acknowledging receipt of Addendum Number 1 in the sealed envelope with the Bid, prior to 2:00 P.M. on 2/23/2010. Failure to sign and include this Addendum with the Bid will be grounds for rejection of the entire Bid.

Brad T. McKeachnie, Procurement/Compliance Analyst

Company Name

Signature

Printed Name

Questions with Answers in **bold** to RTC10-5 for telephony equipment

1. The quantity for the Contact Center License upgrade on the RFP is 30. According to the Nortel Software history, we should only be upgrading 25 licenses from Release 4 to 7.

Answer: Equipment Pricing Sheet REVISED and attached to reflect a Qty of 25

2. The IFB calls for a Dell Signaling Server and 2 co-res signaling servers. From a cost perspective, RTC could purchase 3 co-res signaling servers to reduce costs. The Co-res Signaling servers can easily handle the environment at RTC.

Answer: Thank you for your suggestion. Please quote the servers as requested for our consideration.

3. The RFP calls for one switch to network via SIP. The other two PBX's are networked via H323. Switches cannot network via different IP networking protocols. It has to either be all SIP or all H323. We recommend SIP because most technologies are going towards a SIP environment. SIP future proofs RTC ability to network with other SIP applications in the future if desired.

Answer: Equipment Pricing Sheet REVISED to reflect the request for SIP

4. The IFB asks to quote 48 SIP access ports. This is not required because we have the ability to convert ITG trunks to SIP trunks at zero cost.

Answer: Conversion of ITG trunks to SIP at zero cost is planned. Part is listed to assist in identifying upgrade strategy.

5. Item #3 and #4 above have the same part number. The part number provided is to add SIP Access Ports.

Answer: Conversion of ITG trunks to SIP at zero cost is planned. Part is listed to assist in identifying upgrade strategy.

6. Some of the cables on the Equipment Pricing Sheet can be removed upon final configuration.

Answer: Please note in your response any items that you feel are not required.

7. The line items below will not be required when purchasing PASS with the upgrade.

| 200 | NTE957LL | SW Upgrade Existing to R6 (up to 1199 users per system) |
|-----|----------|---|
| 128 | NTE957LL | SW Upgrade Existing to R6 (up to 1199 users per system) |
| 128 | NTE957LL | SW Upgrade Existing to R6 (up to 1199 users per system) |

Answer: Please note in your response any items that you feel are not required.

8. The Dell Server that you are requesting is not a Nortel part number or a part number from Dell.

Answer: It was suggested that the Dell Server was preconfigured from Nortel with specific partitions as required for the Call Center. Please provide full documentation for any alternatives proposed as explained under "Equal or Better" pricing.

| <u>Qty</u> | <u>Part</u> | Description | Bid Price* | Extended Price | Equal or Better** |
|------------|--------------------|---|------------|----------------|-------------------|
| 1 | CoResDELL-R3030V.7 | Contact Center Co-Res Dell Server Standard Rack-Mount | | | |
| 1 | NTDW41AAE6 | Dell R300 COTS Server for Enterprise | | | |
| 1 | NTHU65AC | CS 1000 Applications on COTS Server - R6 | | | |
| 1 | N0134948 | Full Application Site Move Summary Sheet | | | |
| 1 | N0134948 | Full Application Site Move Summary Sheet | | | |
| 1 | NT9S34AA | CC License File on Media | | | |
| 1 | NT9S55AA | SCCS 5.0 Base Upg.to CCM 7.0 | | | |
| 25 | NT9S55GA | SCCS 5.0 to CCM 7 Voice Agent Upgrade Increment 1-49 | | | |
| 1 | NT9S80AC | Contact Center License Information Sheet | | | |
| 1 | NT9S89PA | Contact Center R7 Nodal Indicator | | | |
| 1 | NTAG81AAE6 | Audio Cable (RoHS) | | | |
| 1 | NTAG81BAE6 | CABLE 9PIN D-SUB MALE TO 9PIN | | | |
| 1 | NTAG81CAE6 | Media Card Maint. Cable (3m) | | | |
| 1 | NTAG81DAE6 | VLAN Maintenance Cable (RoHS) | | | |
| 1 | NTAK20ADE5 | Stratum 3 Clock Contr.PCP Assy | | | |
| 1 | NTAK20ADE5 | Stratum 3 Clock Contr.PCP Assy | | | |
| 1 | NTBK80BA | Ground Bar Assy Opt11 | | | |
| 1 | NTDU0606E6 | Cable Ethernet RJ45 M-M 25cm | | | |
| 1 | NTDU0606E6 | Cable Ethernet RJ45 M-M 25cm | | | |
| 1 | NTDU0606E6 | Cable Ethernet RJ45 M-M 25cm | | | |
| 1 | NTDU22JB | Media Gateway 1000E Cabinet (AC) | | | |
| 1 | NTDU22JB | Media Gateway 1000E Cabinet (AC) | | | |
| 1 | NTDU41GA | Media Card 32S (MC 32S) | | | |
| 3 | NTDW63BAE5 | Kit Plastics Upgrade M1 Option 11C Cabinet | | | |
| 2 | NTDW63BAE5 | Kit Plastics Upgrade M1 Option 11C Cabinet | | | |
| 1 | NTDW63BAE5 | Kit Plastics Upgrade M1 Option 11C Cabinet | | | |
| 1 | NTE960UA | System Upgrade to Communication Server 1000E CPPM Standard Availability | | | |
| | | SRG50 Rls3 to Rls5 SW Upgrade Kit for CS1000 (incl Auth code and BCM Upgrade kit and | | | |
| 1 | NTM496GA | SRG50 Docs) | | | |
| 1 | NTE960UA | System Upgrade to CS 1000E CPPM CS/SS Co-Res | | | |
| 1 | NTE960UA | System Upgrade to CS 1000E CPPM CS/SS Co-Res | | | |
| 48 | NTE980JA | SIP Access Port License | | | |
| 24 | NTE980JA | SIP Access Port License | | | |
| 24 | NTE980JA | SIP Access Port License | | | |
| 4 | NTE980RA | RAN CON Licence | | | |
| 1 | NTM440EA | Compact Flash S/W Inst Kit Single Proc (CPPM) R6 with 512 MB Compact Flash, 128 MB CF | | | |
| 1 | INTIVITATOLA | backup, 1 GB CF, Doc DVD, dongle | | | |
| | NTM440EA | Compact Flash S/W Inst Kit CS/SS Co-Res (CPPM) R6 with 2 GB Compact Flash, 128 MB CF | | | |
| 1 | | backup, 1 CPPM SigServ Hard Drive Kit, 1 GB DRAM Memory, Doc DVD, dongle kit | | | |
| | | | | | |
| 1 | NTM440EA | Compact Flash S/W Inst Kit CS/SS Co-Res (CPPM) R6 with 2 GB Compact Flash, 128 MB CF | | | |
| | | backup, 1 CPPM SigServ Hard Drive Kit, 1 GB DRAM Memory, Doc DVD, dongle kit | | | |

| Qty | <u>Part</u> | <u>Description</u> | Bid Price* | Extended Price | Equal or Better** |
|------------|-------------|---|------------|-----------------------|-------------------|
| 1 | NTRX26NPE6 | DB9F TO DB9F SERIAL CABLE NULL MODEM | | | |
| 1 | NTTK14ABE6 | PWR Cord 9.9ft 11CM 125VA | | | |
| 1 | NTTK14ABE6 | PWR Cord 9.9ft 11CM 125VA | | | |
| 1 | NTTL43AD | SRS Upgrade Upgd TM 4.0 | | | |
| 1 | NTWB17AB | System Upgrade Kit to CS 1000E CPPM - SA | | | |
| 1 | NTWB17AB | System Upgrade Kit to CS 1000E CPPM - SA | | | |
| 1 | NTWB17AB | System Upgrade Kit to CS 1000E CPPM - SA | | | |
| 2 | NTWB22AB | Conversion to MG 1000E | | | |
| 1 | NTWB22AB | Conversion to MG 1000E | | | |
| 2 | NTZE07EA | Callpilot 2 Voice Channel Package | | | |
| 1 | NTZE32KA | CallPilot 3.0/4.0 to 5.0 IPE Upgrade Package | | | |
| 1 | NTZE4002 | CP Upgrade Code (NO Charge) | | | |
| 1 | NTZE4002 | CallPilot Upgrade Order Specifier Code (No Charge) | | | |
| 350 | NTZE56FA | CallPilot R3.0 to R5.0 Software Upgrade Fee | | | |
| 1 | NTZE58AA | CallPilot 5.0 IPE 201i Disk Drive Upgrade Kit | | | |
| | | | | | |
| 200 | SVOM0068 | SRS - SW Upg L/L to R6.0 | | | |
| 128 | SVOM0068 | SRS - SW Upg L/L to R6.0 | | | |
| 128 | SVOM0068 | SRS - SW Upg L/L to R6.0 | | | |
| | | | | | |
| 200 | NTE957LL | SW Upgrade Existing to R6 (up to 1199 users per system) | | | |
| 128 | NTE957LL | SW Upgrade Existing to R6 (up to 1199 users per system) | | | |
| 128 | NTE957LL | SW Upgrade Existing to R6 (up to 1199 users per system) | | | |
| | | | | | |
| 200 | GU4300882 | CS1000 Partner Assurance Software Support - Plus-SL882 - (Villanova) | | | |
| 128 | GU4300882 | CS1000 Partner Assurance Software Support - Plus-SL882 - (Terminal) | | | |
| 128 | GU4300882 | CS1000 Partner Assurance Software Support - Plus-SL882 (Sutro) | | | |
| 350 | GU4300883 | CallPilot Partner Assurance Software Support - Plus - SL883 | | | |
| 25 | GU4300AK1 | Contact Center Manager - 1-499 Standard Voice Agents Partner Assurance Software | | | |
| 4 5 | GU4300AK1 | Support PLUS Upgrades -SLAK1 | | | |
| 1 | GU4300AJ1 | Contact Center Manager - Nodal Base System PASS Plus upgrades - SLAJ1 | | | |
| | | Total Freight Charges | | | |
| | | Total Bid Price | | |] |

^{*} Please enter "No Bid" or "Equal or Better" if not pricing Exact item.

^{**} Enter "Equal or Better" part number in column provided and submit documentation to substantiate that the proposed equipment is Equal or Better in all respects (referencing part #) on separate sheet.