

Central Services Administrative Center 111 East North Street Eureka, MO 63025-1229

636.733.2032 636.733.8851 Fax wichowskiterra@rsdmo.org

November 26, 2018

Request for Proposal: RFP1118WREREPAIR - Weight Room Equipment Repairs

Addendum # 1

Questions - Schedule A

- Question 1: Row 11 references a Star Trac treadmill with serial number PL40601275. The manufacturer shows this as an invalid serial number. Please can you confirm the serial number for this machine?
- Response: The serial number for this machine is either P140601275 or PI40601275. Additional information for this machine is listed below:
 - Model: 6500 PRO IR
 - SKU: 9-6531-SUSAP0
- Questions 2: Rows 10 and 12 have duplicate serial numbers for two Star Trac treadmills. Please can you provide the correct serial numbers.
- Response: The serial number for each is listed below:
 - Row 10: TREN0801-U05243
 - Row 12: TREN0801-U05587
- Questions 3: Rows 27-29 mention the repair of a wheel for three Precor EFX 5761 machines. Please can you clarify which wheel(s) need repair for each machine?
- Response: Provide a quote for repair/replacement of the following parts for each machine:
 - Axle wheel
 - Wheel
 - Transport wheel
- Questions 4: Rows 27-30 mention the repair of a rear cover for four Precor EFX 5761 machines. Please can you clarify which rear cover needs repair on each machine?
- Response: The rear assembly cover of each machine requires repair or replacement. A picture of one rear assembly cover is shown in Exhibit A.
- Question 5: Rows 32-33 mention the repair of link covers for two Life Fitness Cross Trainers. Please can you clarify which link cover needs repair on each machine?
- Response: The entire rear cover of each machine requires repair or replacement. A picture of one rear cover is shown in Exhibit B.
- Question 6: Row 33 mentions the repair of a front cover for one Life Fitness Cross Trainer. Please can you clarify which front cover needs repair?
- Response: Provide a quote for repair/replacement of the following parts for each machine:

- Entire front cover
- Entire clevis cover

A picture of the damaged cover of one machine is shown in Exhibit C.

- Question 7: Row 44 references a Strive Leg Press. Please can you provide a serial number and/or pictures of this machine?
- Response: The only visible number on this machine is 32251, as shown in Exhibit D.
- Question 8: Line 60 mentions the repair of a hand grip for a Vision T9800 Treadmill. Please can you clarify which hand grip needs repair?
- Response: The left hand grip needs repair.
- Question 9: Line 70 mentions the repair of upholstery for a roman chair, bench press and chest press. Please can you provide manufacturer and model number information for these repairs?
- Response: The information is shown below:
 - Roman Chair:
 - Make: Champion Barbell
 - o Model: Unknown
 - Bench Press
 - o Make: Champion Barbell
 - o Model: Unknown
 - Chest Press
 - o Make: Matrix
 - o Model: Unknown
- Question 10: Line 72 mentions a Magnum shoulder press. Please can you provide the model for this machine?
- Response: This is a Magnum Retro Series shoulder press.
- Question 11: Line 73 mentions a bicep curl. Please can you provide the name of the manufacturer?
- Response: The manufacturer and model number are unknown.
- Question 12: Line 81 mentions a treadmill. Please can you provide the brand, model and serial number of this treadmill?
- Response: This is a Star Trac treadmill. The model and serial number are unknown.

[REMAINDER OF PAGE INTENTIONALLY LEFT BLANK]

EXHIBITS

<u>Exhibit A</u>



Exhibit C



<u>Exhibit B</u>

<u>Exhibit D</u>



